

Final Reclamation and Stormwater Inspection

Date: 4/4/24

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 429893

Inspection Document #: 713900513

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Latham 14-12 Facility
Location ID: 429893



Photo 1. The photo was taken at the tank battery location facing Southeast. The photo illustrates the facility is no longer in use and dominated by tumbleweeds with some Crested wheatgrass and Intermediate wheatgrass.

Note - Barbed wire fencing remains around the entirety of the disturbance.

Photo 2. The photo was taken at the tank battery location facing South. Refer to the comment for photo 1.

Inspection Photos
Location Name: Latham 14-12 Facility
Location ID: 429893



Photo 3. The photo was taken at the tank battery location facing Northeast. Refer to the comment for photo 1.



Photo 4. The photo was taken at the tank battery location facing East. The photo illustrates what appears to be the flowline corridor that has been fenced in and is dominated by tumbleweeds.

Inspection Photos
Location Name: Latham 14-12 Facility
Location ID: 429893



Photo 5. The reference photo was taken at the tank battery location facing North. The photo illustrates reference areas are dominated by Sand sagebrush, wheatgrass and russian thistle.