

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 4/8/2024



Location Entrance – Photo #00445



Wellheads – Photo #00447

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 4/8/2024



Separators – Photo #00449



Tank Battery – Photo #00446

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 4/8/2024



Lack of Stabilization – Photo #00450



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00451**