

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



**Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 262 yards from Battlement Creek. Location is in close proximity to Rule 411a Surface Water External Buffer
Section/Township/Range: 15 7S95W**



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



Photo # 3241 Stockpiled soils with no BMP's

Photo # 3242 Stockpiled soils with no BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



Photo # 3243 Stockpiled soils with no BMP's



Photo # 3244 Stockpiled soils with no BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



Photo # 3245 Lack of stabilization/compaction/insufficient tracking BMP's & soils stockpile with no BMP's in the background



Photo # 3246 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



Photo # 3247 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3248 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



Photo # 3249 Lack of stabilization/compaction/insufficient tracking BMP's

Photo # 3250 Lack of stabilization/compaction/insufficient tracking BMP's