

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/02/2024

Submitted Date:

04/03/2024

Document Number:

713900494**FIELD INSPECTION FORM**Loc ID 327419 Inspector Name: Hansen, Logan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246865	WELL	PA	08/11/2022	GW	123-14662	HSR-ROSS 15-24A	RI

General Comment:

This is a Final Reclamation inspection in response to Form 4 Final Reclamation Complete Notice (Document #403713165). The well was plugged and abandoned 08/11/2022.

Inspected Facilities									
Facility ID:	246865	Type:	WELL	API Number:	123-14662	Status:	PA	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental			
Spills/Releases:			
Type of Spill: _____		Estimated Spill Volume: _____	
Comment: <div>Remediation Project #24064 has been closed and approved on 2/2/2023 .</div>			
Corrective Action: _____		Date: _____	
Reportable: _____		GPS: Lat _____	Long _____
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well Complaint:			
DWR Receipt Num: _____		Owner Name: _____	GPS : _____
Field Parameters: <div></div>			
Sample Location: _____		Comment: _____	

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: This inspection is in response to Form 4 (Document #403713165) Final Reclamation complete notice. The plugged and abandoned well is located on an active location however a riser remains at the well location. All risers must be removed within 3 months of plugging and abandoning of a well. The well was plugged 08/11/2022, therefore the riser should have been removed by 11/11/2022.

Corrective Action:	Remove all risers per Rule 1004.a.	Date	05/03/2024
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403742104	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6494143
713900495	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6494140