

Inspection Photos

API: 071-09433

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/2/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the access road that goes across the drainage to the location. The access road and abandoned location have not been reclaimed.



Inspection Photos



Photo 2. Facing southeast toward the location which was abandoned in 2011. The location has not been recontoured and reclaimed..



Inspection Photos



Photo 3. Facing southwest toward the vertical unstable cut slope which is approximately 50 ft. high.



Inspection Photos



Photo 4. There is storage of various supplies and materials at the location.



Inspection Photos



Photo 5. Facing northwest toward the access road that goes across the canyon drainage.

