

## Inspection Photos

Location Name: CONAGRA B-65N64W/30SESE

Location #: 311508



**Photo #1**

**Conagra B 29-33 (123-25921) Wellsite**

**Plugged & Abandoned | PA**

*Cut / Capped*

*~ 5 yds.*

*prior photo*



**Photo #2**

**Conagra B 29-33, Menoni B30-16 Battery site**

**Abandoned: ALL Equipment Removed**

*prior photo*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Location Name: CONAGRA B-65N64W/30SESE

Location #: 311508



**Photo #3**

**Conagra B 29-33** Wellsite

**Plugged & Abandoned | PA**

*Cut / Capped*

**CA: Unnecessary Equipment**



**Photo #4**

**Conagra B 29-33** Wellsite

**Plugged & Abandoned | PA**

*Wellsite entrance*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources