

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 4/9/2024



Location Entrance – Photo #00472



Wellheads – Photo #00473

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 4/9/2024



Separators – Photo #00475



Tank Battery – Photo #00477

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 4/9/2024



Debris in Tank Battery – Photo #00479



Open-Ended Load Line – Photo #00478

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 4/9/2024



Open-Ended Load Line – Photo #00480



Open-Ended Load Line – Photo #00481

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 4/9/2024



Open-Ended Load Line – Photo #00482



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources