

Inspection Photos

Location Name: CONAGRA B-65N64W/30SESE

Location #: 311508



Photo #1

Conagra B 29-33 (123-25921) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 5 yds.

prior photo



Photo #2

Conagra B 29-33, Menoni B30-16 Battery site

Abandoned: ALL Equipment Removed

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CONAGRA B-65N64W/30SESE

Location #: 311508



Photo #3

**Conagra B 29-33 Wellsite
Plugged & Abandoned | PA**

Cut / Capped

CA: Unnecessary Equipment
prior photo



Photo #4

**Conagra B 29-33 Wellsite
Plugged & Abandoned | PA**

Wellsite entrance

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CONAGRA B-65N64W/30SESE

Location #: 311508



Colorado Energy & Carbon Management Commission
Weld County
+40.364536,-104.585403
240° SW
2024-04-10 14:15

Photo #5

Conagra B 29-33 Wellsite

Plugged & Abandoned | PA

Cut / Capped

CA: Resolved. ALL Equipment removed.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources