

Inspection Photos

04/04/2023

Operator: LARAMIE ENERGY LLC 10433

Location ID: 311744

Inspection Doc: 69620572

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 311744



Photo 1: Photo taken from the south end of the Location, facing north. Though desirable plant establishment is evident, establishment is sparse and not uniform. Location remains predominantly bare, or vegetated by Undesirable Plant Species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 311744



Photo 2: Photos taken from the east end of the Location facing southwest and northwest. Photo example showing Location is predominantly bare and expose soils, or vegetated by Undesirable Plant Species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 311744



Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 311744



Photo 4: Photo taken from central areas of the Location. See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources