

Inspection Photos

04/04/2023

Operator: LARAMIE ENERGY LLC 10433

Location ID: 312625

Inspection Doc: 696205730

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312625



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312625



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312625



Photo 3: Location signage, east end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312625



Photo 4: Photo taken from the north end of the Location, facing west. Desirable perennial vegetative establishment throughout the Location is sparse, and not progressing towards ECMC uniform standards.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312625



Photo 5: Photo taken from the south end of the Location, facing east. Desirable perennial vegetative establishment throughout the Location is sparse, and not progressing towards ECMC uniform standards. Green vegetation within the photos are predominantly annual forbs, such as *Ranunculus testiculatus*.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312625



Photo 6: Photo taken from the northeast end of the Location. Runoff on the north end of the Location is resulting in a gully. Operator appears to have previously placed rock socks within the channel. BMP alone is inadequate to manage runoff and allow for proper stormwater discharge.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312625



April 4, 2024



April 4, 2024

Photo 7: Photo taken from the northwest end of the Location. Photo example showing erosion logs have not been maintained in proper functioning condition. No other BMPs in conjunction with erosion logs observed. Erosion degradation evident.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources