

Tank Battery : South



Tank Battery : Sign



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

Inspection Number: **709200111**

Well Head : South East



Well Head Sign - Incorrect





COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
SPRINGDALE STORAGE 2
Location ID: **312147**

Nearby Risers : South West



Well Head Storage Equipment: South



Inspection Number: **709200111**