

Inspection Photos  
Location Name: HSR-Mnookin 4-17, Craven 31-17  
Location ID: 332618



Photo 1: Wellhead Sign

Photo 2: PA Wellhead

**Inspection Photos**  
**Location Name: HSR-Mnookin 4-17, Craven 31-17**  
**Location ID: 332618**



**Photo 3: Wellhead Sign**

**Photo 4: Wellhead**

Inspection Photos  
Location Name: HSR-Mnookin 4-17, Craven 31-17  
Location ID: 332618



Energy & Carbon Management Commission  
40.31941, -104.69451, 1423.7m, 128°  
Apr 10, 2024 08:55:20



Energy & Carbon Management Commission  
40.31947, -104.69439, 1421.1m, 102°  
Apr 10, 2024 08:55:35

Photo 5: Tank Battery Sign

Photo 6: Tank Battery

Inspection Photos  
Location Name: HSR-Mnookin 4-17, Craven 31-17  
Location ID: 332618



Photo 7: Capacity not legible

Photo 8: Equipment