

Inspection Photos
Location Name: Oxford Farms G unit 1
Location ID: 321301



Energy & Carbon Management Commission
40.11464, -105.07672, 5000.0ft, 254°
04/11/2024 11:12:02



Energy & Carbon Management Commission
40.11463, -105.07723, 5012.0ft, 234°
04/11/2024 11:16:45

Photo 1 Location.

Photo 2 TB & signs.

Inspection Photos
Location Name: Oxford Farms G unit 1
Location ID: 321301



Photo 3 TB.

**Photo 4 Gas Meter Run, card indicates current calibration.
ECD & Horizontal Heated Separator.**

Inspection Photos
Location Name: Oxford Farms G unit 1
Location ID: 321301



Photo 5 Gas Meter Run, card indicates current calibration.
ECD & Horizontal Heated Separator.

Photo 6 WH & sign.