

Inspection Photos

04/04/2023

Operator: LARAMIE ENERGY LLC 10433

Location ID: 312524

Inspection Doc: 696205732

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312524



Photo 1: Photos 1-2 taken from the Location. Photos provide an overview of the Location from north, east, south to west. Final reclamation is considered “in-process” and appears to be progressing towards 1004 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312524



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312524



Photo 3: Photo example of desirable vegetative establishment observed on the Location. Though annual grasses and weeds were evident, desirable establishment is also observed and appears to be progressing towards uniform requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312524



April 4, 2024



April 4, 2024

Photo 4: Photo taken from the access road. Vegetation observed predominantly Noxious weeds (Halogeton).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312524



Photo 5: Location signage.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources