

Inspection Photos

04/04/2023

Operator: LARAMIE ENERGY LLC 10433

Location ID: 312622

Inspection Doc: 696205736

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312622



Photo 1: Location entrance, signage.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312622



Photo 2: Photos taken from the Location. Final reclamation “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312622



Photo 3: Final Reclamation in process.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312622



Photo 4: Photos taken from the west end of the Location. Photos examples showing Halogeton establishment on the site.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312622



April 4, 2024

Photo 5: Reclamation in process along access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312622



Photo 6: Photos examples showing Halogeton establishment along the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources