

Inspection Photos

04/04/2023

Operator: LARAMIE ENERGY LLC #10433

Location ID: 312620

Inspection Doc: 696205742

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312620



Photo 1: Location signage and access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312620



Photo 2: Photos taken from the southern end of the Location, facing northwest and northeast. Final Reclamation “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312620



Photo 3: Photo example show areas on the Location where additional seeding may be necessary to ensure uniform vegetative establishment.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources