

Inspection Photos

API: 061-06370

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 4/10/2024

County: Prowers



Inspection Photos



Photo 1. Facing southeast toward the location.



Inspection Photos



Photo 2. Facing toward the onsite tank battery.



Inspection Photos




Photo 3. Facing toward the TA'd well. The pumpjack is not in use and needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06370 | Date: 4/10/2024