

## Inspection Photos

Location Name: CVR/5-63-32\_33 NWSW

Location ID: 449306



**Photo #1**

**CVR/5-63-32\_33 NWSW South Pad**

Wellsite(s): 5

**4: Producing | PR; 1: Shut-In | SI**

*N → S*

*North & South Wellpad entrance*



**Photo #2**

**CVR 5-63-32-4841D2 (123-44252)**

**Abandoned Location | AL**

*~ 5 yds.*

*Location NOT built, NOT drilled.*

*On existing Active location w/ active well(s).*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources