

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403750837

Date Received:

04/11/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000472

Inspection Date: 02/22/2024

FIR Submit Date: 02/26/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326623

Location Name: ALVA SHORT GAS UNIT A-N33N9W Number: 7SESW County: _____

Qtrqr: SESW Sec: 7 Twp: 33N Range: 9W Meridian: N

Latitude: 37.114298 Longitude: -107.867648

FACILITY - API Number: 05-067-00 Facility ID: 326623

Facility Name: ALVA SHORT GAS UNIT A-N33N9W Number: 7SESW

Qtrqr: SESW Sec: 7 Twp: 33N Range: 9W Meridian: N

Latitude: 37.114298 Longitude: -107.867648

CORRECTIVE ACTIONS:

1 ☒ CA# 192432

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 03/04/2024

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator Comment: Weedy debris removed and properly disposed of.

ECMC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.



Date: 03/12/2024

Date of Completion: 04/10/2024

Unused equipment removed.

Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

Comment: CA completed. See attached completion photos.

Print Name: Gabby Riley

Signed:

Title: Permitting Specialist I

Date: 4/11/2024 11:27:22 AM

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403750837	FIR RESOLUTION SUBMITTED
403750855	Alva Short A2; CA completion photos

Date Run: 4/15/2024 Doc [#403750837]