

## Inspection Photos

Location Name: CHEVRON USA INC, SKINNER RIDGE-65S98W/25NENW

Location ID: 336047

Date: 4/11/2024



Location Entrance – Photo #00579



Wellheads – Photo #00582

# Inspection Photos

Location Name: CHEVRON USA INC, SKINNER RIDGE-65S98W/25NENW

Location ID: 336047

Date: 4/11/2024



Separator Housing – Photo #00585



Tank Battery – Photo #00583

## Inspection Photos

Location Name: CHEVRON USA INC, SKINNER RIDGE-65S98W/25NENW

Location ID: 336047

Date: 4/11/2024



Line Heaters – Photo #00586