

Work Completion Report

Contractor: US Hydro

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
PSC 8-9			4/11/2024

Work Summary	Reclamation Type	Land Use
Remove road base from access road and haul to gobbler. Import topsoil and level road. Import topsoil and fill subsidence at wellhead. Deep cross rip, spread compost, disc, seed, straw mulch and crimp	Final	Pasture

One-Call Number	Red Zone Rep	Red Zone Date
B407302553		3/20/2024

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Evaluate and complete final reclamation practices	Normal	No	Location(s): PSC 8-9 Notes: Access road removed in field. Export any roadbase, import top soil, alleviate compaction, rip, disk, compost and seed. Address any disturbances around former well head.

COMPLETION DETAILS

Total Area Affected: **43,560 sq ft**
 Seed Mix: **Dryland Pasture (15.00 lbs)**
 Crop Type:
 Soil Type: **Clay**
 Stabilization Date: **4/11/2024**
 Seeding Date: **4/10/2024**
 Mulch: **Straw at (No Rate)**
 Straw Bales: **3 bales at Round (Contractor-supplied)**
 Soil Amendment Type: **Compost**
 Soil Amendment Rate: **NA**
 Imported Top Soil: **435.00 Tons**
 Top Soil Source:
 General Notes:

LOCATION INFO

Location(s) – Name: PSC 8-9

COGCC ID: **331920**

Well APIs at Location: **12321568**

Land Rep:

Land Owner:

Rec Contractor PO(s):

Vendor PO(s):

Billing Notes:

Legal Address: **(WELD) SENE 9 3N67W**

Topsoil Source:

Variance Notes:

Private Utility Notes:

Wildlife Restrictions: **Located within BAEA Winter Night Roost. Work limited to 10am-2pm or after 3/15. Discuss with OXY rep before job kickoff.**

General Notes:

COGCC Doc #'s:

Initial Reclaim Complete Date:

Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Red Zone
Description:

OXY GROUND DISTURBANCE & PIPELINE CONSTRUCTION RED ZONE CHECK LIST	
LOCATION: PSC 8-9	
DATE: 3/20/24	
PROJECT ENGINEER: _____	
1-CALL REQUEST#: 8407302553	
OCCIDENTAL REP: Scott Taylor	PHONE#: 781-535-2420
EXCAVATOR REP: Brian Schoencker 200 BilgerHeiser 970-931-1555	PHONE#: 970-654-1554 970-654-5577
This form is to be used in conjunction with OXY Tailgate Safety Meeting & Excavation Inspection Forms.	
OXY REP	EXC REP
BEFORE ANY EXCAVATION IS STARTED THAT DAY:	
<i>Call XCEL before working around former well</i>	
<input checked="" type="checkbox"/>	Verify ALL known lines/wires within 100' of right-of-way (ROW) have been flagged by the operator of the utility or their designee. <i>DGP outside Row to E</i>
<input checked="" type="checkbox"/>	Verify that GIS Portal and other sources of information have been reviewed by OXY and Contractor personnel.
<input checked="" type="checkbox"/>	Identify and overhead hazards and take appropriate steps to manage them. Use a spotter, wire sleeve, or other methods as necessary. <i>Trees along access, electric lines</i>
<input checked="" type="checkbox"/>	If survey stakes are "down", the ROW must be re-staked prior to excavation. If the locate markings are down, the excavator must request a "refresh" with One-Call. The "refresh" must NOT be done by an OXY employee or designee, but by the original marking organization.
<input checked="" type="checkbox"/>	Verify that the contractor has walked the ditch line in front of the excavator (prior to excavation) to verify all locate markings are accounted for. If available, a locator should assist the contractor.
<input checked="" type="checkbox"/>	Verify the One-Call Locate Request documents are furnished by the Contractor and have been reviewed by OXY and Contractor personnel.
<input checked="" type="checkbox"/>	Verify the One-Call Locate Request is current (more than 48 hours and less than ³⁰ days old) for the section of ROW that will be excavated. This needs to be documented with copies. <i>4/15/24</i>
<input checked="" type="checkbox"/>	Check that the excavating equipment operator has been properly trained and is qualified to operate the equipment.
<input checked="" type="checkbox"/>	Verify the excavating employees are experienced, have adequate equipment and PPE.
OXY REP	VERIFY ALL EXISTING UTILITIES HAVE BEEN MARKED:
<input checked="" type="checkbox"/>	Check fences and fields for markers, signs, valves, stub-outs, etc. <i>NA, none in work area</i>
<input checked="" type="checkbox"/>	Drive the perimeter of the day's excavation area. Verify road crossings and lines to be crossed. <i>NA</i>
Noting surface encumbrances such as tank batteries, wells, valves, phone pedestals, electrical cattle guard, gate, fencing, stumps, <i>found on access, cattle</i> junction boxes or other signs of underground utilities. <i>pedestal markings well P&A</i>	
Noting any evidence of previous excavations along the ROW	

Photo Name: Seed Mix
Description:

From: 490 East 10th Ave., Suite 701
Denver, CO 80229

Mix Name: **OXY - Dryland - Initial**

Mix # **234636**

Dryland - Initial

% Pure	Common Name	Variety
18.40	TRITICALE	QuickGua
14.72	RYEGRASS, PERENNIAL	Oro Verde
14.72	SWITCHGRASS	Blackwell
13.01	BROMEGRASS, SMOOTH	Lincoln
12.86	INTERMEDIATE WHEATGRASS	Manifest
11.15	PUBESCENT WHEATGRASS	Manska
6.14	SIDE OATS GRAMA	Butte
1.94	BLUE GRAMA	Lovington
1.84	BUFFALOGRASS	Texoka
1.02	BEE PLANT, ROCKY MOUNTAIN	VNS

0.81 Other Crop

3.34 Inert Matter

0.07 Weed Seed

Net Weight 15.00 Lbs. PLS

Coverage: 1.000 Acre

NOTICE TO BUYER LIMITATIONS OF WARRANTIES AND REMEDIES

Crop yield and quality are dependent upon many factors beyond the control of the seller. The labeled seller warrants that all seed sold has been labeled true and that the seed conforms to the label description, within recognized tolerances. NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY, ARE MADE BY THE SELLER. FOR ANY PURPOSE, THERE ARE NO WARRANTIES WHICH EXTEND BEYOND THE

No claim shall be asserted against the labeled seller unless Buyer reports to the seller within a reasonable time after the date of purchase.

Photo Name: Pre-Completion

Description:




Photo Name: Post-Completion

Description:



Photo Name: Well head subsidence

Description:



Photo Name: Mow weeds

Description:



Photo Name: Topsoil subsidence

Description:



Photo Name: Remove roadbase

Description:



Photo Name: Roadbase in access

Description:



Photo Name: Import topsoil

Description:



Photo Name: Deep rip
Description:



Photo Name: Spread compost

Description:



Photo Name: Disc
Description:



Photo Name: Seed

Description:



Photo Name: Straw mulch

Description:




Photo Name: Crimp

Description:

