

# State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

03/29/2024

Document Number:

403735699

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

### Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

### Operator Information

ECMC Operator Number: <u>10808</u>	Contact Person: <u>Joshua JAny</u>
Company Name: <u>COPPER LAND RESOURCES LLC</u>	Phone: <u>(303) 250-6765</u>
Address: <u>9470 HOMESTEAD DR</u>	Fax: <u>( )</u>
City: <u>FREDERICK</u> State: <u>CO</u> Zip: <u>80504</u>	Email: <u>copperlandresources@gmail.com</u>

### Identification Information

API Number: <u>05 - -</u>	ECMC Facility ID: <u>268515</u>	Initial Form 19 or 27 Document number: _____
Facility Name: <u>LINDA #2</u>	Facility Number: _____	Facility Type: <u>PIT</u>
Location QtrQtr: <u>NENE</u>	Section: <u>30</u>	Township: <u>2S</u>
	Range: <u>52W</u>	Meridian: <u>6</u>
	County: <u>WASHINGTON</u>	Field Name: <u>QUEST</u>
Federal, Indian or State Lease Number: _____		

### Information Submitted By:

Company Name: <u>CGRS, Inc.</u>	Agent Name: <u>Drezden Kinnaird</u>	Title: <u>Project Manager</u>
Phone Number: <u>970-493-7780</u>	Email: <u>dkinnaird@cgrs.com</u>	

### Rule 909.J Inspection Information

Date the Pit was Inspected 02/21/2024

On inspection the Pit was:  Unlined  Lined  Fenced  Netted

### Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: <u>237995</u>	Facility Name: <u>LINDA 2</u>	Facility Type: <u>Oil and Gas Well</u>
Location: QtrQtr: <u>NENE</u>	Sec: <u>30</u>	Twp: <u>2S</u>
	Range: <u>52W</u>	Meridian: <u>6</u>
County Name: <u>WASHINGTON</u>	Latitude: <u>39.855850</u>	Longitude: <u>-103.239550</u>

### Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: <u>118406</u>	Document Name: <u>EDD</u>	File Name: <u>2024_0221_Linda 2_909j_EDD_AA05366.xlsx</u>
Sample Type: _____	Matrix: _____	
Facility ID: <u>237995</u>	Sample ID: <u>657858</u>	Sample Name: <u>Linda 2</u>
	Sample Date: <u>02/21/2024</u>	
Collection Point: <u>PitDis</u>	Matrix: <u>WATER</u>	Pre Post: <u>Rule 909.j subsequent sample</u>
Project Number: <u>20037</u>	Remediation Number: _____	Complaint Number: _____
	NOAV Number: _____	
Inspection Number: _____	Spill Number: _____	Laboratory: _____
	Lab Sample ID: <u>AA05366</u>	

### Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
237995	403735712	2024_0221_Linda 2_909j_Analytical Report_AA05366.pdf	Analytical Laboratory Report	PDF

**Sample ECMC Well Related:**

Sample ID	API Num	Well Name & Num	Sample Reason
657858	121-10498	LINDA 2	Rule 909.j subsequent sample

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	04/16/2024
Total: 1 comment(s)		