

## Inspection Photos

Location Name: CHEVRON USA INC, SKR-65S98W/36NWSW

Location ID: 336048

Date: 4/11/2024



Location Entrance – Photo #00625



Wellheads – Photo #00626

## Inspection Photos

Location Name: CHEVRON USA INC, SKR-65S98W/36NWSW

Location ID: 336048

Date: 4/11/2024



Separator Housing – Photo #00628



Tank Battery – Photo #00629



## Inspection Photos

Location Name: CHEVRON USA INC, SKR-65S98W/36NWSW

Location ID: 336048

Date: 4/11/2024



Stored Supplies/Equipment – Photo #00636



Stored Supplies/Equipment – Photo #00637



## Inspection Photos

Location Name: CHEVRON USA INC, SKR-65S98W/36NWSW

Location ID: 336048

Date: 4/11/2024



Debris – Photo #00639



Unprotected Soil Stockpile – Photo #00631



## Inspection Photos

Location Name: CHEVRON USA INC, SKR-65S98W/36NWSW

Location ID: 336048

Date: 4/11/2024



**Unprotected Soil Stockpile – Photo #00634**



**Unprotected Soil Stockpile/Debris – Photo #00638**