

Interim Reclamation and Stormwater Inspection

Date: 04/16/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 319123

Inspection Document #: 708201145

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Gold - 65N66W
Location ID: 319123



Photo 1. Emergency contact information has been updated/changed on signage at the location.

Inspection Photos
Location Name: Gold - 65N66W
Location ID: 319123



Photo 2. NFPA placard at tank is peeling/faded/cracked.

Inspection Photos
Location Name: Gold - 65N66W
Location ID: 319123



Photo 3. Taken from the western side of the location. Colorado List B Noxious Weed (russian olive) has been removed from the location's interim areas. Operator shall continue to manage the location for noxious/undesirable vegetation.

Inspection Photos
Location Name: Gold - 65N66W
Location ID: 319123



Photo 4. Taken from the western side of the location; see comments in Photo 3.

Inspection Photos
Location Name: Gold - 65N66W
Location ID: 319123



Photo 5. Taken from the center portion of the location; see comments in Photo 3.

Inspection Photos
Location Name: Gold - 65N66W
Location ID: 319123



Photo 6. Taken from the eastern side of the location; see comments in Photo 3.

Inspection Photos
Location Name: Gold - 65N66W
Location ID: 319123



Photo 7. Taken from the northern side of the location; see comments in Photo 3.



Photo 8. Trash observed near the location's entrance. Operator should consider posting against illegal dumping, installing cameras and/or installing gates to deter such activity.