

Inspection Photos

Location Name: SIEBRING-65N63W/32NWNE

Location ID: 306088



Photo #1

Siebring CNE-32 (123-23967) Wellsite

Temporarily Abandoned | TA



Photo #2

Siebring 41-32, 31-32, 32-32, 42-32, CNE-32

Battery site

Inactive | Shut-down

Equipment Documented; Loc ID: 332237



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources