

Inspection Photos

API: 071-08376

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/15/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along access road. The access road is not stabilized and it appears a vehicle went off the road causing rutting disturbance that will need to be repaired.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. There is erosion and vehicle rutting near the location that needs to be repaired..



Inspection Photos



Photo 3. Facing northwest toward the wellsite.



Inspection Photos



Photo 4. There is oil in the engine skid that needs to be cleaned up..

