

Inspection Photos

API: 071-09040

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/15/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the access road. The access road has been stabilized with additional road base.



Inspection Photos



Photo 2. The culverts along the road are maintained.



Inspection Photos



Photo 3. The access road has been repaired with additional gravel.



Inspection Photos



Photo 4. Facing east along the access road to the wellsite.

