

Inspection Photos

API: 071-07087

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/15/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. A culvert was installed at this intersection for proper drainage.



Inspection Photos



Photo 2. The access road has been repaired with additional gravel.



Inspection Photos



Photo 3. Facing southwest toward the wellsite.

