

Inspection Photos

API: 071-08812

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/15/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along access road. This area of the access road has erosion that needs to be repaired.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing back southeast at the area of the access road that has eroded.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing north toward the TA'd wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources