

Inspection Photos

April 12th, 2024

Operator: Morning Star Operating LLC - 10755

Location ID: 320906

Inspection Document #: 714000662

La Plata County, CO

Township: NWSE 13 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Schumacher 32-6 13-3
Location ID: 320906

4/12/24
+37.016234,-107.451351
36° NE



Photo 1. Overview of the well pad disturbance from the access point facing center.



Inspection Photos

Location Name: Schumacher 32-6 13-3

Location ID: 320906



Photo 2. View of location/well sign attached to unused fencing on location and not being displayed properly.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06239

Inspection Photos

Location Name: Schumacher 32-6 13-3

Location ID: 320906



4/12/24
+37.016146,-107.451468
222° SW



4/12/24
+37.016113,-107.451577
60° NE

Photo 3. Evidence of sediment transport moving off location. Current storm water BMPs installed along the western edge of the access road at the access point are inadequate and not functioning properly.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06239

Inspection Photos
Location Name: Schumacher 32-6 13-3
Location ID: 320906



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of the southern interim reclamation area facing east.
Vegetation comprised of mostly rabbitbrush.

API #: 007-06239

Inspection Photos

Location Name: Schumacher 32-6 13-3

Location ID: 320906

4/12/24

+37.016113,-107.451577

284° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of the reference area comprised of rabbit brush and greasewood.

API #: 007-06239