

Inspection Photos

April 12th, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 320872

Inspection Document #: 714000666

Archuleta County, CO

Township: NWSE 14 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Peterson 32-6 14-1
Location ID: 320872



Photo 1. View of the well disturbance from the access point facing center.



Inspection Photos

Location Name: Peterson 32-6 14-1

Location ID: 320872




Photo 2. View of weedy kochia/russian thistle weedy debris dominating produced water tank/berm area.

Inspection Photos
Location Name: Peterson 32-6 14-1
Location ID: 320872



Photo 3. Weedy debris observed around pump jack.



Inspection Photos
Location Name: Peterson 32-6 14-1
Location ID: 320872

4/12/24
+37.014674,-107.468165
261° W



Photo 4. Reference area comprised of western wheatgrass and smooth brome.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06187