

Inspection Photos

April 12th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325216

Inspection Document #: 714000680

La Plata County, CO

Township: SESW 15 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McKeen 1
Location ID: 325216



4/12/24
+37.012820,-107.491040
350° N

Photo 1. View of the well disturbance taken from the access point facing center. No other equipment was observed on location.



4/12/24
+37.010291,-107.485220
323° NW

