

# Inspection Photos

April 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326143

Inspection Document #: 714000681

La Plata County, CO

Township: NESW 15 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: McKeen 32-6-15 1  
Location ID: 326143

4/12/24  
+37.015546,-107.491875  
71° E



Photo 1. View of the well disturbance taken from the access point facing center.



API #: 067-07544



Inspection Photos  
Location Name: McKeen 32-6-15 1  
Location ID: 326143



4/12/24  
+37.016042,-107.491488  
110° E



Inspection Photos  
Location Name: McKeen 32-6-15 1  
Location ID: 326143



**Photo 3.** Impacted surface material corrective action identified in the previous inspection doc #712700844 has been addressed/resolved.



Inspection Photos  
Location Name: McKeen 32-6-15 1  
Location ID: 326143



4/12/24  
+37.014947,-107.492083  
122° SE