

Inspection Photos

April 12th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325008

Inspection Document #: 714000682

La Plata County, CO

Township: NESW 16 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sutton 1
Location ID: 325008



4/12/24
+37.020482,-107.502295
220° SW

Inspection Photos
Location Name: Sutton 1
Location ID: 325008




Photo 2. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Sutton 1
Location ID: 325008



Photo 3. Cardinal photos taken from the center of the disturbance. Left photo facing south, right photo facing west.

Inspection Photos
Location Name: Sutton 1
Location ID: 325008



Photo 4. View of the western edge of the project area where vegetation is sparse. Surface owner equipment storage and activities appear to be affecting vegetation progression within the western portion of the disturbance.

API #: 067-05075

Inspection Photos
Location Name: Sutton 1
Location ID: 325008



Photo 5. View of the reference area comprised mostly of smooth brome.