

Inspection Photos

Location Name: VAN WYKE-65N63W/32SE1W

Location ID: 332268



Photo #1

Van Wyke 22-32 (123-22064) Wellsite
Temporarily Abandoned | TA



Photo #2

Van Wyke 22-32 Wellsite(s)
Wellsite entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: VAN WYKE-65N63W/32SENW

Location ID: 332268



Photo #3

Van Wyke 4-2-32, 21-32, 22-32 Battery site

Inactive | Shut-down

Equipment Documented; Loc ID: 332695



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources