

Inspection Photos

04/12/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054

Inspection Doc: 696205754

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 3: Photo shows signage at battery; signage does not comport with 605 requirements. Operator emergency number no longer works.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 4: Photos taken from the battery facility. Photo shows lines at tanks missing required cap/plug.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 6: Photo taken from the interim areas on the south end of the Location. Photo shows Noxious Weed (Mullein) establishment on the Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 6: Photo shows the only marked anchor observed on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 7: Photos 7-8 taken from the north end of the Location. Photos show stormwater and erosion control BMPs to manage runoff from the working pad surface are missing or insufficient, resulting in degradation and sediment deposition at the interim areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection
Operator Name: TEP ROCK
Location II



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection
Operator Name: TEP ROCK
Location I



Photo 9: Photos taken from the east end of the Location. See comments under photo 7.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 10: Photos taken from the southeast end of the Location.
See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335054



Photo 11: 2023 Google Earth aerial imagery. Circles highlight areas of stormwater concern identified within photos 7-10.