

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403753869

Date Received:

04/15/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000547

Inspection Date: 03/12/2024

FIR Submit Date: 03/14/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333515

Location Name: KOON GAS UNIT-N33N9W Number: 19NESW County: _____

Qtrqtr: NESW Sec: 19 Twp: 33N Range: 9W Meridian: N

Latitude: 37.086730 Longitude: -107.870460

FACILITY - API Number: 05-067-00 Facility ID: 333515

Facility Name: KOON GAS UNIT-N33N9W Number: 19NESW

Qtrqtr: NESW Sec: 19 Twp: 33N Range: 9W Meridian: N

Latitude: 37.086730 Longitude: -107.870460

CORRECTIVE ACTIONS:

1 ☒ CA# 193084

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 03/19/2024

Response: CA COMPLETED

Date of Completion: 04/11/2024

Operator Comment: Impacted surface material cleaned and removed.

ECMC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

ECMC Representative:	acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.		
2	✔	CA# 193085	
Corrective Action:	Comply with rule 605. Install or repair sign.		Date: 04/13/2024
Response:	CA COMPLETED		Date of Completion: 04/11/2024
Operator Comment:	Produced water sign installed.		
ECMC Decision:	Approved via an AMI		
ECMC Representative:	Per photo included in attachment provided by operator the sign has been installed.		

OPERATOR COMMENT AND SUBMITTAL

Comment: CA completed. See attached completion photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley
 Title: Permitting Specialist I

Signed: _____
 Date: 4/15/2024 10:32:54 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403753869	FIR RESOLUTION SUBMITTED
403753882	Koon 1E; CA completion photos

Total Attach: 2 Files