

Inspection Photos
Location Name: LD19-16 Tank Battery
Location ID: 447247



Energy and Carbon Management Commission
40.73202, -103.89822, 4789.1ft
04/15/2024 12:59:30



Energy and Carbon Management Commission
40.73232, -103.89913, 4784.0ft
04/15/2024 13:00:01

Photo 1 – Signs at Entrance

Photo 2 – Produced Water Tanks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: LD19-16 Tank Battery
Location ID: 447247



Photo 3 – Crude Oil Tanks



Photo 4 – ECD

Inspection Photos
Location Name: LD19-16 Tank Battery
Location ID: 447247



Photo 5 – Gas Meter Houses



Photo 6 – VRU

Inspection Photos
Location Name: LD19-16 Tank Battery
Location ID: 447247



Photo 7 – Compressor



Photo 8 – Separators

Inspection Photos
Location Name: LD19-16 Tank Battery
Location ID: 447247



Photo 9 – Maintenance Tank



Photo 10 – Separators

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102



Photo 11 – Bulk and Compressor



Photo 12 – Instrumental Air Unit