

# Final Reclamation Inspection

April 11, 2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 318080

Inspection Document #: 697505270

Weld County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ADDIE M. KING GAS UNIT 1

Location ID: 318080



**Photo 1.** Google Earth aerial imagery from 10/6/2013 during active operations. The historic land use was cropland.



Inspection Photos

Location Name: ADDIE M. KING GAS UNIT 1

Location ID: 318080



**Photo 2.** Google Earth aerial imagery from 2/19/2024 after plugging operations. Imagery illustrates a land use change to housing development.



Inspection Photos  
Location Name: ADDIE M. KING GAS UNIT 1  
Location ID: 318080



**Photo 3.** Photo taken from the well location, facing East. Photo illustrates that all equipment has been removed.



**Photo 4.** Photo taken from the tank battery area, facing East. See comments under Photo 3.

Inspection Photos

Location Name: ADDIE M. KING GAS UNIT 1

Location ID: 318080



**Photo 5.** Photo taken from the western access road, facing East. Photo illustrates the access road has been superseded by housing development.

