

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2024

Submitted Date:

04/19/2024

Document Number:

712100004**FIELD INSPECTION FORM**Loc ID 414031 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10619Name of Operator: INSPIRE OIL & GAS INCAddress: 1773 WESTBOROUGH DRIVE, SUITECity: KATY State: TX Zip: 77449**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Ritz, Bo	713-269-4969	britz@inspireoilandgas.com	
Wolfe, Stephen		stephen.wolfe@state.co.us	
Binschus, Chris		chris.binschus@state.co.us	

General Comment:

On April 15, 2024 ECMC Environmental Staff (Alex Fischer) and Reclamation Staff (Chris Binschus) conducted an environmental field inspection of Inspire Oil and Gas Inc.'s Silver Spur Minerals 35-2H, API 05-057-06490. Weather was sunny and temperature 40 degree F. For the most recent field inspection report of this facility, refer to document #690900214.

Location was not accessible due to snow accumulation at gate entrance and along lease road.

Operator is no longer active in the State of Colorado.

Spill ID 479967 is still active in the COGIS database.

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: [Spill ID 479967 is still active in the COGIS database.](#)Corrective Action: [Comply with the 900 Series Rules including but not limited to Rules 912.b.\(6\). and 913.](#)

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

ECMC Comments

Comment

User

Date

On April 15, 2024 ECMC Environmental Staff (Alex Fischer) and Reclamation Staff (Chris Binschus) conducted an environmental field inspection of Inspire Oil and Gas Inc.'s Silver Spur Minerals 35-2H, API 05-057-06490. Weather was sunny and temperature 40 degree F. For the most recent field inspection report of this facility, refer to document #690900214.

fischera

04/18/2024

Location was not accessible due to snow accumulation at gate entrance and along lease road.

Operator is no longer active in the State of Colorado.

Spill ID 479967 is still active in the COGIS database.

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712100006	20240414 Inspection Photos (1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6516977