

Inspection Photos

April 18th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 325961

Inspection Document #: 714000689

La Plata County, CO

Township: SWNW 20 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Allison Unit 116
Location ID: 325961



Photo 1. View of the project area taken from the northern edge facing southwest.

Inspection Photos
Location Name: Allison Unit 116
Location ID: 325961



Photo 2. Cardinal photos taken from the center of the disturbance. Left photo facing north right photo facing east.

Inspection Photos
Location Name: Allison Unit 116
Location ID: 325961



Photo 3. Cardinal photos taken from the center of the disturbance. Left photo facing south right photo facing west.

Inspection Photos
Location Name: Allison Unit 116
Location ID: 325961



Inspection Photos
Location Name: Allison Unit 116
Location ID: 325961

4/18/24
+37.003903,-107.529879
189° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of sage brush, juniper and perennial grasses.

API #: 067-07243