

Inspection Photos

April 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326132

Inspection Document #: 714000694

La Plata County, CO

Township: NESW 18 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lopez 32-6-18 1
Location ID: 326132



Photo 1. View of the well disturbance taken from the access point facing center.



Inspection Photos
Location Name: Lopez 32-6-18 1
Location ID: 326132



Photo 2. Unused vehicle chock trash observed on location.



Inspection Photos
Location Name: Lopez 32-6-18 1
Location ID: 326132



Photo 3. View of weedy russian thistle debris observed on location.

Inspection Photos
Location Name: Lopez 32-6-18 1
Location ID: 326132



Photo 4. View of deteriorating muffler pipe impacting surface material.

Inspection Photos
Location Name: Lopez 32-6-18 1
Location ID: 326132



Photo 5. View of damaged access gate, maintenance is required.

Inspection Photos
Location Name: Lopez 32-6-18 1
Location ID: 326132



Photo 6. Reference area is an active pasture that is being grazed by cattle, minimal vegetation observed.