

Inspection Photos

Location Name: DUNN-65N64W/7SESW

Location ID: 309728



Photo #1

Dunn 7B (123-25311)

Abandoned Location | AL

Location NEVER built.

~ 15 yds.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUNN-65N64W/7SESW
Location ID: 309728



Photo #2

Dunn 7B

Abandoned Location | AL

Location NEVER built.

Nearby Oil / Gas Production Facility / Battery

2023 Google Earth Imagery



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUNN-65N64W/7SESW
Location ID: 309728




Photo #3

Dunn 7B

Abandoned Location | AL

Location NEVER built.

No disturbance or evidence of oil / gas activity.

2012 Google Earth Imagery



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources