

Inspection Photos
Location Name: PLUMB-65N64W/7SENE
Location #: 323470



Photo #1
Plumb #3 (123-13079) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 150 yds.



Photo #2
Plumb #3, #2, #4 Battery site
Abandoned: ALL Equipment Removed

