

Inspection Photos
Location Name: PLUMB-65N64W/7SWNE
Location #: 323471



Photo #1
Plumb #4 (123-13080) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 260 yds.



Photo #2
Plumb #3, #2, #4 Battery site
Abandoned: ALL Equipment Removed

