

Inspection Photos
Location Name: PLUMB-65N64W/7NENE
Location #: 323469



Photo #1
Plumb #2 (123-13078) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 40 yds.



Photo #2
Plumb #3, #2, #4 Battery site
Abandoned: ALL Equipment Removed

