

Inspection Photos

Location Name: TEP Rocky Mountain LLC GRAND VALLEY W-3 Pad

Location # 334804



Photo # 4325 From entrance to location



Photo # 4326 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC GRAND VALLEY W-3 Pad

Location # 334804



Photo # 4327 Location



Photo # 4328 Location

Inspection Photos
Location Name: TEP Rocky Mountain LLC GRAND VALLEY W-3 Pad
Location # 334804



Photo # 4329 Location



Photo # 4340 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC GRAND VALLEY W-3 Pad

Location # 334804




Photo # 4341 Tank label damaged & missing required information



Photo # 4342 Open ended pipe/wildlife hazard