

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Latham 14-12 Facility

Loc ID: 429893

Inspection: 713900513



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F

CA: Weed debris in the form of tumbleweeds were observed throughout the location. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds. Comply with Rule 606 to remove weed debris.

CA Resolution: Operator has reported that the location has been mowed to address undesirable vegetation and tumbleweeds have been cleared to comply with Rule 606. Operator has also noted that the location/flowline corridor has been inter-seeded, and straw crimped to promote vegetation.

CA: Barbed wire fencing remains around the tank battery facility and flowline corridor. It does not appear there is currently any cattle grazing in the area and so fencing should be removed. Remove fencing to comply with Rule 1004.

CA Resolution: Operator has reported that the barbed wire fencing has been removed around the flowline corridor and facility pad to comply with Rule 1004.