

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403637596

Date Received:

12/27/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

BACA, DAVE

719-859-4066

dbaca@ogrisop.com

WARD, GIENA

719-220-4041

gward@ogrisop.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 695108686

Inspection Date: 09/25/2023

FIR Submit Date: 10/20/2023

FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC

Company Number: 10758

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 333906

Location Name: HILL RANCH-634S67W Number: 33SWSW County: LAS ANIMAS

Qtrqtr: SWS Sec: 33 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.036230 Longitude: -104.899620

FACILITY - API Number: 05-071- -00 Facility ID: 256540

Facility Name: HILL RANCH Number: 33-13R

Qtrqtr: SWS Sec: 33 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.036230 Longitude: -104.899620

CORRECTIVE ACTIONS:

1 ☒ CA# 185627

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D.

Date: 11/20/2023

Response: CA COMPLETED

Date of Completion: 12/21/2023

THE OILY WASTE IN THE ENGINE SKID HAS BEEN REMOVED AND MECHANICAL MAINTENANCE PERFORMED. THE SOIL STAINS AROUND THE SKID HAVE ALSO BEEN REMOVED AND THE SELF

Operator Comment: INSPECTION PROCESS REVIEWED.

ECMC Decision: Approved via an AMI

ECMC Representative:

2 ☒ CA# 185628

Corrective Action: Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 10/23/2023

Response: CA COMPLETED

Date of Completion: 12/21/2023

Operator Comment: THE OILY WASTE IN THE ENGINE SKID HAS BEEN REMOVED AND MECHANICAL MAINTENANCE PERFORMED. THE SOIL STAINS AROUND THE SKID HAVE ALSO BEEN REMOVED AND THE SELF INSPECTION PROCESS REVIEWED.

ECMC Decision: Approved via an AMI

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED, SEE PHOTO LOG FOR DETAILS

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed:

Title: ENVIRONMENTAL

Date: 12/27/2023 2:15:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403637596	FIR RESOLUTION SUBMITTED
403637623	PHOTO LOG

Total Attach: 2 Files