

Inspection Photos

04/18/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335680

Inspection Doc: 696205761

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



Photo 1: Photos show the 3 produced water tanks on the Location. Secondary containment measure at tanks inadequate in size to contain at least 150% of the volume of the largest single Tank within the containment; berm along the western areas of the BMP also missing.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



Photo 2: Continued from photo 1. Photo example showing Lines at tanks are missing cap/plug.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



Photo 3: Photos examples showing unused equipment on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



April 18, 2024

Photo 4: Photo example showing anchors on the Location observed missing required marking.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



Photo 5: Tank battery facility missing signage per Rule 605.e.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



Photo 6: Photos taken from the interim areas on the west end of the Location. Photo shows areas that have not been recontoured/regraded and reclaimed. Pipe equipment (arrow) and soil stockpile evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



Photo 7: Photos taken from the west end of the Location. Photo shows stormwater and erosion control BMPs to manage runoff from the Location in a manner that minimizes erosion, degradation and sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335680



Photo 9: Continued from photo 7. Photo shows gully erosion due to runoff.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources